INSTALLATION RESTORATION PROGRAM

Final DECISION DOCUMENT UST SITE 450

117th Refueling Wing Alabama Air National Guard Birmingham Airport Birmingham, Alabama

January 1997



DTIC QUALITY INSPECTED &

Appeaved he public releases

Distribution University

19970915 122

Form Approved OMB No. 074-0188

REPORT DOCUMENTATION PAGE

Public reporting burden for this collection of information is estimated to average 1 hour per response, includin g the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. Send comments regarding this burden estimate or any other aspect of the collection of information, including suggestions for reducing this burden to Washington Headquarters Services, Directorate for Information Operations and Reports, 1215 Jefferson Dayis Highway. Suite 1204, Arlington, VA 22202-4302, and to the Office of Management and Budget, Paperwork Reduction Project (0704-0188), Washington, DC 20503.

Davis nighway, Suite 1204, Annington, VA 22202	2-4002, and to the Office of Management a	na baager, r aperment	Troduction Troject (c. c. c.	50), 1745g.c, 2 2 2 2 2 2 2 2		
1. AGENCY USE ONLY (Leave blank)	2. REPORT DATE Jan 97	3. REPORT TYPE	AND DATE COVERED			
4. TITLE AND SUBTITLE DECISION DOCUMENT, UST 450, 117 TH REFUELING WING, Alabama Air National Guard, Birmingham Airport, Birmingham, Alabama						
6. AUTHOR(S) CH2M Hill, Inc.						
7. PERFORMING ORGANIZATION NAME(S) AND ADDRESS(ES)			8. PERFORMING ORGANIZATION REPORT NUMBER			
CH2M Hill, Inc.	Hazardous Waste Remed Actions Program, Mart Marietta Energy Syste Oak Ridge, TN 37840	in				
9. SPONSORING/MONITORING AGENCY NA	ME(S) AND ADDRESS(ES)		10. SPONSORING/MONITORING AGENCY REPORT NUMBER			
ANG/CEVR 3500 Fetchet Ave Andrews AFB MD 20762- 5157						
11. SUPPLEMENTARY NOTES This is part of IRP Site 13 (ST13) at Birmingham IAP.						
12a. DISTRIBUTION/AVAILABILITY STATEMENT unlimited distribution			12b. DISTRIBUTION CODE			
13. ABSTRACT (Maximum 200 Words)						
The Installation Restoration Program was initiated by the Air National Guard (ANG) to evaluate potential contamination to the environment caused by past practices at its installations. During the 1987 Preliminary Assessment (PA), ten abandoned underground storage tanks (USTs) were identified at nine sites. During the 1991 Site Investigation, geophysical surveys failed to find a UST at this location (northern-most point on curve of B Street). The report documents no further action need be taken at this the UST site.						
14. SUBJECT TERMS Installation Restoration Program, No Further Action			15. NUMBER OF PAGES 12 pages			
Decision Document, UST, I Airport, Air National Gu		16. PRICE CODE				
17. SECURITY CLASSIFICATION OF REPORT	18. SECURITY CLASSIFICATION OF THIS PAGE	19. SECURITY CL		20. LIMITATION OF ABSTRACT		
General	General	General		none		

INSTALLATION RESTORATION PROGRAM

DECISION DOCUMENT SITE UST 450

117 AIR REFUELING WING ALABAMA AIR NATIONAL GUARD BIRMINGHAM AIRPORT BIRMINGHAM, ALABAMA

Submitted to:

AIR NATIONAL GUARD READINESS CENTER ANDREWS AIR FORCE BASE, MARYLAND

Modified and Submitted by:

HAZARDOUS WASTE REMEDIAL ACTIONS PROGRAM MARTIN MARIETTA ENERGY SYSTEMS, INC.
OAK RIDGE, TENNESSEE

for the
U.S. DEPARTMENT OF ENERGY
UNDER CONTRACT NO. DE-AC05-840R21400

Prepared by:

CH2M HILL, INC. MONTGOMERY, ALABAMA

JANUARY 1997

DTIC QUALITY INSPECTED &

Copies of this report may be purchased from the:

National Technical Information Service 5285 Port Royal Road Springfield, Virginia 22161

Federal Government agencies and contractors registered with the Defense Technical Information Center should direct requests for copies of this report to:

Defense Technical Information Center 8725 John J. Kingman Road, Ste 0944 Ft. Belvoir, VA 22060-6218

CONTENTS

Acrony Execut	ymsii ive Summary	ii 1
1.	Introduction	
2.	Background	2 5 5
3.	Control Measures	6
4.	Conclusions	6
FIGUI	RES	
1 2 3	Location Map, Birmingham Air National Guard UST Location Map UST 450 Site Map	4

ACRONYMS

AANG Alabama Air National Guard

ANG Air National Guard

ANGRC Air National Guard Readiness Center

DOD Department of Defense
DOE Department of Energy
GPR Ground Penetrating Radar

HAZWRAP Hazardous Waste Remedial Actions Program

IRP Installation Restoration Program

NGB National Guard Bureau

PA/SI Preliminary Assessment/Site Investigation

RD/RA Remedial Design/Remedial Action

RI/FS Remedial Investigation/Feasibility Study

SI Site Investigation

UST Underground Storage Tank

EXECUTIVE SUMMARY

As part of the Installation Restoration Program (IRP), the Air National Guard Readiness Center (ANGRC), previously known as the National Guard Bureau (NGB), and Alabama Air National Guard (AANG) requested field observation and sampling during the removal of Underground Storage Tank (UST) 450. The investigation was begun to determine the presence or absence of contamination and the risk to public health and environment, if any, associated with past operations at this site.

This document was prepared to review the available data, to evaluate alternative actions, to make recommendations concerning future action, and to fulfill the requirements and objectives of the National Environmental Policy Act.

The UST 450 site was investigated during the field survey task, but no tank was found.

Because no UST was found, it is recommended that this site be removed from further IRP activities and that no further action is required.

1. INTRODUCTION

The objectives of the Decision Document are to present the history of Underground Storage Tank (UST) 450 at Birmingham's Alabama Air National Guard (AANG) facility, to discuss observations made while investigating the tank, and to present conclusions and decisions about the disposition of the UST site. Decisions are based on regulations set forth in the site investigation (SI) work plan dated November 1989.

Figure 1 shows the general location of the AANG facility in Birmingham. Figure 2 shows the specific location of UST 450 on the base. Evaluations are based on criteria set forth in the <u>Site Investigation Work Plan, Alabama Air National Guard</u> (CH2M HILL, Inc., November 1989).

2. BACKGROUND

2.1 PROGRAM BACKGROUND

The Air National Guard Readiness Center (ANGRC), through the Air National Guard (ANG), initiated an Installation Restoration (IRP) in response to the policies of the Department of Defense (DOD). The IRP was developed as a phased program for identifying and addressing environmental contamination caused by past practices at ANG installations.

As a part of the IRP, the ANGRC entered into an interagency agreement with the Department of Energy (DOE), under which the DOE will provide technical assistance for implementing this program. The Hazardous Waste Remedial Actions Program (HAZWRAP), as a DOE contractor, is responsible for managing this effort under the interagency agreement.


The IRP, along with other national hazardous waste cleanup programs, follows the terminology and procedures of the National Contingency Plan:

- PA/SI Preliminary Assessment/Site Investigation
- RI/FS Remedial Investigation/Feasibility Study
- RD/RA Remedial Design/Remedial Action

This Decision Document is written to provide the basis for the decision not to do any further work.

Birmingham Air National Guord, Birmingham, Alab

3



2.2 SITE DESCRIPTION

The 117th Tactical Reconnaissance Wing is located next to and north of the Birmingham Municipal Airport, Birmingham, Alabama. This AANG installation has been active at its present location since 1938. Through the years, the base has had several missions, with past and present operations involving the use of USTs for containment of heating fuels, diesel fuels, and jet propulsion fuels.

UST 450's contents were unknown based on information found during the initial investigation of the AANG facility. Figure 3 shows the suspected location of UST 450.

2.3 ENVIRONMENTAL SETTING

2.3.1 Geology

The bedrock beneath the Base consists of the Ketona Dolomite and Knox Group. A mottled-colored cherty clay residuum, resulting from the dissolution of the bedrock, overlies dolomites of these units and averages 30 feet in thickness over the base. Some areas of the Base have visible outcrops of dolomite and chert boulders which are isolated in the clay residuum; chert float can be seen at the surface base-wide.

The residual cherty clays are generally homogeneous, although slight changes in the amount of chert, plasticity and stiffness are present. Dolomitic sand lenses are gravelly clays are present, generally occurring at the contact of clay and bedrock.

2.3.2 Hydrogeology

The uppermost aquifer at the Base is the Knox aquifer. The top of the aquifer is the saturated permeable interface between the residual clay and the bedrock. The clay materials above the bedrock are also generally saturated at shallow depths, 10 to 15 feet below land surface. These clays generally do not yield significant quantities of water.

The direction of groundwater flow in both the clay residuum and the Knox is to the south; a downward vertical component exists in the clay residuum. Data from slug testing of monitoring wells completed in the clay indicate an average hydraulic conductivity of 9.02E-4 ft/day. Because of the low permeabilities exhibited by the residual clays, lateral transport is inhibited.

2.3.3 Water Utilization

Drinking water in the Birmingham is provided by city/county utilities from surface water sources. The municipal water source nearest the Base is the Cahaba River, located approximately 20 miles to the east. Residences adjacent to the Base have been served by the municipal water system for about 60 years.

2.4 TANK REMOVAL OBSERVATIONS

A program to evaluate abandoned USTs at the Birmingham AANG facility included identifying abandoned tank locations, sampling tank contents, preparing tank removal plans and specifications, removing tanks and contaminated soil, and evaluating investigation-derived wastes after the removal effort was complete.

During the Tank Survey Task to identify the location and sizes of the tank, magnetic devices and Ground Penetrating Radar (GPR) were used to identify tank boundaries and sizes. A concrete slab was found during this task in the suspected UST area and was further investigated by excavating a trench and tunnel to a distance of 7.5 feet under the slab. The UST was not found. Excavation determined that the results of the magnetic instrument survey were a result of feedback from shallow rock formations found approximately seven feet below ground surface.


Further review of aerial photography and base records revealed minimal information about the UST 450 site. UST 450 was not found, and no further action was taken.

3. CONTROL MEASURES

Because UST 450 was not found and therefore not included in the UST removal project, control measures used to consider adverse effects of potential contamination were not considered for screening, identification, and evaluation.

4. CONCLUSIONS

Past operations at the UST 450 site led to this investigation because of possible soil and water contamination. A field survey task used to identify the UST location and size did not reveal the presence of a UST at this site.



,			
Signature:_	DAVID C. VAN GASBECK Chief, Environmental Division Air National Guard Readiness Center	Date:	
Signature:_	Alabama Department of Environmental	Date: Management	

Because no UST was found, it is recommended that this site be removed from further

IRP activities and that no further action be taken.